

General Environmental Incident Summary

Incident: 3287 **Date/Time Notice:** 4/15/2014 **DEM Incident No:**

Responsible Party: Conoco Phillips

Date Incident: 4/14/2014 **Time Incident:** 10:15 **Duration:**

County: Dunn **Twp:** 147 **Rng:** 95 **Sec:** 28 **Qtr:**

Lat: 47.53040 **Long:** -101.79260 **Method:** Navigation quality GPS

Location Description: CCU Corral Creek 11-28 MBH, From the junction of Hwy. 200 and Hwy. 22 in Killdeer, go North on Hwy. 22 for 13.2 mi. just past mile marker 117 turn East on CCU Main road for 4 miles, then turn left onto location. It's on the north side of the CCU road.

Submitted By: Jesse Radebaugh

Affiliation:

Address: 505 4th Street SW

City: Watford City

State: ND

Zip:

Received By:

Contact Person:

513 4th Street SW
Watford City, ND

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Pump Leak

Description of Released Contaminant: Oil Based Mud

Volume Spilled: 2.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Pump Hose Rupture

Risk Evaluation:

No immediate risk associated

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

No environmental impact, spill was contained within the primary containment. Residuals were removed and mixed with fly ash and disposed of properly.

Action Taken or Planned:

Shut in system and replace defective hose.

Wastes Disposal Location: Recycled back into system

Agencies Involved:

Updates

Date: 4/16/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

Release of oil-based mud remained on an E&P location according to the report. Report forwarded to NDIC for oversight.